

SECTION A: ERROR DETAILS

Bugzilla Error Number	BUG4318
Description of Error: Shell and Tube Heat Exchanger - Pressure Drop Excluding Elevation Result Incorrect	
Comments: The pressure drop excluding elevation result is different from the pressure drop result when the number of baffle passes on the shell side changes.	
Corrected Version:	8.12.8.4472

SECTION B: WORKAROUND

Workaround Description: This is a post processing result – it can be calculated by the user from other results on the nodes and element.

SECTION C: SIGNOFF

Person Responsible for Fix:		
Eugene van Heerden		2021/08/06
Name	Signature	Date
Person Responsible for Review:		
Tiaan Dercksen		2021/08/09
Name	Signature	Date